Epoxy.com Material Safety Data Sheet OSHA's Hazard Communication Standard, 29 CFR 1910.1200.

IDENTITY: Epoxy	.com Product Bondaid		
SECTION I			
Manufacturer:	Epoxy Systems'™	Emergency Number: 1-800-633-8253	
Address:	20774 West Pennsylvania Ave	Telephone Number: 352-489-1666	
	Dunnellon,FL34431	Date Prepared: 02/2012	
SECTION II - HAZAR	DOUS INGREDIENTS/IDENTITY		
HazardousCompone	ents CA S# O	SHAPEL Hazard Limits %	
Butadiene 100	00	ppm <. 1%	
Formaldehyde		3 ppm <.1%	
SECTION III - PHYSI	CAL/CHEMICAL CHARACTERIS	STICS	
Boiling Point:	>212° F	Specific Gravity (H ₂ 0 =1): 1.01 - 1	1.03
Vapor Pressure (mm	n Hg.): as water	Melting Point: N/A	
Vapor Density (AIR =	= 1): as water	Evaporation Rate: as water	
Solubility in Water:	Dispersible pH 10-11	(Butyl Acetate = 1)	
Appearance and Od			
Appearance and Out			
	AND EXPLOSION HAZARD DAT	۸	
Flash Point (Method		n	
Flammable Limits:		A	
Extinguishing Media	a: Water, carbon dioxide, dry che	mical	
		eathing apparatus should be worn.	
	-	catiling apparatas should be worn.	
Unusual Fire and Ex	plosion Hazards: None known		
SECTION V - REACT			
Stability: Stable	Conditions to Avoid:		
Incompatibility: Non			
		acular waight budraaarbana may ba farmad	
-		ecular weight, hydrocarbons may be formed	
Hazardous Polymeri	ization: Will Not Occur Co	nditions to Avoid: None known	

SECTION VI - HEALTH HAZARD DATA

Route(s) of Entry: Inhalation? Yes Ski n? No Ingestion? Yes

Health Hazards (Acute and Chronic): May cause skin irritation, eyes may cause slight irritation and rash.

Carcinogenicity: NTP? No I ARC Monographs? No OSHA Regulated? No

Signs and Symptoms of Exposure: see above.

Medical Conditions Generally Aggravated by Exposure: None known

Emergency and First Aid Procedures: Skin -Wash with soap and water. Wash contaminated clothing before reuse. Eyes - Flush with water for at least 15 minutes. Inhalation: Remove to fresh air. Ingestion: Do not induce vomiting. Seek medical attention.

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

Steps to Be Taken in Case Material Is Released or Spilled: Clean up with water before allowing to dry. Absorb with sand and shovel to solid waste disposal.

Waste Disposal Method: Dispose of in accordance with Federal, State, and Local regulations.

Precautions to Be Taken in Handling and Storing: Protect from freezing. Keep containers closed.

Other Precautions: Follow OSHA standards for handling Portland cement, concrete or grout.

SECTION VIII - CONTROL MEASURES

Respiratory Protection: NIOSH approved organic respirators in enclosed areas.

Ventilation: Mechanical (General) Good general ventilation.

Protective Gloves: Rubber Gloves

Eye Protection: Safety Glasses

Other Protective Clothing or Equipment: Clean work clothing to prevent skin contact.

Work/Hygienic Practices: Follow practices of good industrial hygiene.