Epoxy Systems, Inc.

20774 West Pennsylvania Ave Dunnellon, FI 34431 Phone 352-489-1666

Material Safety Data Sheet

OSHA's Hazard Communication Standard, 29 CFR 1910.1200.

IDENTITY: Epoxy.com 447 Waterproofing Membrane

SECTION I

Address:

Manufacturer: Epoxy Systems, Inc.

20774 West Pennsylvania Ave

Dunnellon, FI 34431

Emergency Number:

1-800-633-8253 Telephone Number: (352) 489-1666

Date Prepared: 5/2008

SECTION II - HAZARDOUS INGREDIENTS/IDENTITY INFORMATION

Hazardous Components Hazard Limits CAS# **OSHA PEL** ACHIH TLV

Carboxylated S-B Polymer Proprietary N/E Water 7732-18-5 N/E

SECTION III - PHYSICAL/CHEMICAL CHARACTERISTICS

Boiling Point: Specific Gravity ($H_20 = 1$): >212 1.10

Vapor Pressure (mm Hg.): as water **Melting Point:** N/A

Vapor Density (AIR = 1): **Evaporation Rate:** as water as water

Solubility in Water: Butyl Acetate = 1) Dispersible ph 8to 10

Appearance and Odor: Purple viscous liquid, slight odor

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

Flash Point (Method Used): N/A Flammable Limits: LEL N/A UEL N/A

Extinguishing Media: Water, carbon dioxide, dry chemical

Special Fire Fighting Procedures: Wear self-contained breathing apparatus.

Unusual Fire and Explosion Hazards: None known

SECTION V - REACTIVITY DATA

Stability: Stable **Conditions to Avoid:** Relatively non-reactive

Incompatibility: N/A

Hazardous Decomposition or Byproducts: Low molecular weight; hydrocarbons may be formed

Hazardous Polymerization: Will Not Occur Conditions to Avoid: None known

(OVER)

SECTION VI - HEALTH HAZARD DATA

Route(s) of Entry: Inhalation: No Skin: No Ingestion: Yes

Health Hazards (Acute and Chronic): May cause skin irritation or rash, may be eye irritant.

Carcinogenicity: NTP: Not listed IARC Monographs: Not listed OSHA Regulated: Not regulated

Signs and Symptoms of Exposure: See above

Medical Conditions Generally Aggravated by Exposure: None known

Emergency and First Aid Procedures: If ingested, induce vomiting and call a physician immediately. Eyes: Flush with copious amounts of water for 15mins. Skin: Wash with soap and water.

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

Steps to Be Taken in Case Material Is Released or Spilled: Clean up with water before allowing to dry. Absorb with sand and shovel to solid waste disposal.

Waste Disposal Method: Dispose of in accordance with Federal, State and Local regulations.

Precautions to Be Taken in Handling and Storing: Protect from freezing. Keep containers closed.

Other Precautions: Avoid skin and eye contact.

SECTION VIII - CONTROL MEASURES

Respiratory Protection: None normally needed.

Ventilation: Mechanical (General) Good general ventilation.

Protective Gloves: Rubber Gloves Eye Protection: Safety Glasses

Other Protective Clothing or Equipment: To prevent skin contact.

Work/Hygienic Practices: Follow practices of good industrial hygiene.